

ASSEMBLY INSTRUCTIONS


R2-Q5 IMPERIAL ASTROMECH DROID SIXTH SCALE FIGURE

ATTENTION: PLEASE USE CAUTION DURING ASSEMBLY


FOR FURTHER ASSISTANCE:

CALL US (WITHIN U.S.): 1-855-SIDESHOW


CALL US (OUTSIDE U.S.): 1-805-214-2157



On/Off switch and battery compartment access are located underneath the bottom of the head. To insert, line up tabs, push in, and turn clockwise to lock.



(1) Gently tap the front right rectangular panel once to activate front and back lights. (2) Tap twice for projector light. (3) Tap three times to turn off.



To release center foot, push in until it spring releases. To hide foot, push in until the spring locks.

*Please note to be gentle, as some parts of the product may be fragile.

READ THE INSTRUCTIONS CAREFULLY BEFORE USING THE PRODUCT

Product uses three (3) LR44 batteries for the head (located under the dome) and three (3) LR44 batteries for the table (located at the bottom of the table)

1. Non rechargeable batteries should not be charged.
2. Do not mix different types of batteries.
3. Do not mix new and used batteries.

4. Only the recommended type of batteries should be used.
5. Batteries should be inserted and oriented with the correct polarity.
6. Exhausted batteries should be removed from the product.

7. The battery terminals must not be short-circuited.
8. Batteries should be disposed in an appropriate place.
9. Remove batteries when not in use or discharged.



SIDESHOW

For more information visit: SIDESHOW.COM/Instructions